

# Qualified Rigger & Signal Person Cards

To receive a card you must have:

- 1) completed an ironworker apprenticeship
- 2) passed the Local 29 qualified rigger course
- 3) completed and turned in the new O.S.H.A. power line standards quiz  
(a quiz can be picked up at the apprenticeship office)

If you have completed an ironworker apprenticeship but have not passed the Local 29 qualified rigger course you may set up a time with the Apprenticeship coordinator to take the qualified rigger test.

If you have **not** completed an ironworker apprenticeship you will need to attend a qualified rigger and signal person course.

## **Qualified Rigger**

January 14 & 21	Attendance is required on both days.
April 14 & 21	Attendance is required on both days.

## **Qualified Signal Person**

February 11 & 18	Attendance is required on both days.
May 12 & 19	Attendance is required on both days.

To sign up for a class or if you need any additional information regarding Qualified Rigger & Signal Person cards please contact the apprenticeship office at 503-775-0877.

Keith Kordenat  
Apprenticeship Coordinator  
Ironworkers Local 29